



KEN-08-01001

# ***K-COTECH NEWS***

## **Repair Kitchen Floor with ENECRETE DURAQUARTZ!**

This hospital located in Busan, Korea was concerning about their kitchen floor with quarry tiles.

While the hospital staffs were looking for a more cost effective as well as longer term solution, they turned to K-Co-tech's sales director for their kitchen floor for help.

To solve the problem, K-Cotech engineers suggested an unconventional solution: repair the floor with DuraQuartz which has high adhesive with stainless steel.

First of all, we simply cut the tiles by regular depth and width nearby the trench and then filled the gaps with DuraQuartz.

The application has been completed within 1 day, everyone was pleased with the results.



**<Cutting>**



**<Filling DuraQuartz>**



**<Completing applying DuraQuartz>**



**<Completion of the application>**